

NOTA DE CONSTATARE

Nr. 1 / Data 14.07.2020

1. INSTALATIA: Fca H2 – Sector 1 DCS
2. ECHIPAMENT: Media convertor
3. PARAMETRI/CARACTERISTICI ECHIPAMENT:
AT-MC103XL
Allied Telesyn
Single mode fiberfast ethernet media converter - 2 buc.
4. DEFECTIUNI CONSTATATE: nu functioneaza
5. CAUZE POSIBILE: defect electronic
6. FIRMA REPARATOARE: -
7. ANUL PIF: 2009
8. PROPUNERI DE REMEDIERE: Inlocuire
9. DOCUMENTE ANEXATE:
10. SARCINA APROVIZIONARE: PLK
11. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

RACOV. TA A

LUAT LA CUNOSTINTA



DAIS-0924-06.08.20