

TABEL NR. 9
Cu neconformitatile din RK2021 a Supapelor de Siguranta din instalatia FG-CC

Nr. crt	Fabricant	TAG NO	Serie fabricatie	Pozitie montaj	Model(Art. No.)	DN	PN	Locul de montaj	P max.	Pr	Utilaje protejate	Fluid de lucru	Temp de lucru [°C]	Presiunea Burduf	Tip adaptor tija	Tip scaun	Diametrul interior scaun [mm]	Diametrul exterior scaun [mm]	MSA(Aria medie a scaunului) [mm ²]	Neconformitati RK2021	Propuneri Remedieri	OBS
0	1	2	3	4	Art-no. 5	I/E 6	I/E	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21
1	TAI	GE3(T)	28450	GSV10		20/25		GE3(T)	7	7	GE3(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
2	TAI	GE4(T)	28451	GSV11		20/25		GE4(T)	7	7	GE4(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
3	TAI	GE10(T)	28453	GSV13		20/25		GE10(T)	7	7	GE10(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
4	TAI	GE13(T)	28454	GSV14		20/25		GE13(T)	7	7	GE13(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
5	TAI	GE15A,B(T)	28455	GSV15		20/25		GE15A,B(T)	7	7	GE15A,B(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
6	TAI	GE18C,D(T)	28457	GSV16B		20/25		GE18C, D(T)	7	7	GE18C,D(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler
7	TAI	GE20(T)	28458	GSV17		20/25		GE20(T)	7	7	GE20(T)									Scaun si taler deteriorate	Necesita Inlocuire Supapa	Rectificat scaun si taler

Specialist Ment. Mec
Bratu Adrian

Inspector Sef
Alexandru Valentin

Ing. Tehnolog Sector2
Fertic Oleg



TABEL NR. 8
Cu neconformitatile din RK2021 a Supapelor de Siguranta din instalatia CC

Nr. crt	Fabricant	TAG NO	Serie fabricatie	Pozitie montaj	Model(Art. No.)	DN	PN	Locul de montaj	P max.	Pr	Utilitaje protejate	Fluid de lucru	Temp °C	Presiunea de lucru [bar]	Burdul	Tip adaptor tija	Tip scaun	Diametrul interior scaun [mm]	Diametrul exterior scaun [mm]	MSA(Aria medie a scaunului) [mm ²]	Neconformati RK2021	Propuneri Remediere in OT2023	OBS
0	1	2	3	4	Art.-no. 5	I/E 6	I/E 6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	
1	TAI	PSV3	28425/77	PSV3	3211TL4G	40/65		FV12	10.5	10.5	FV12,FE4A-F(N),FE18(T)	motorina,cat alizator	280	5	Da	fara filet	G	22	26	452.16	Burdul spart	Necesita inlocuire supapa	montare fara burduf
2			35688 /1979			20/25		FE24		7	FE24	apa								Surub reglare strans la maxim	Necesita inlocuire la	arc supapa	

Specialist Ment. Mec
Bratu Adrian

Inspector Sef
Alexandra-Valentin

Ing. Tehnolog Sector2
Fertic Oleg

