

## NOTA DE CONSTATARE

Nr. 3 / Data 26.02.2021

1. INSTALATIA: HPM – ARIA1
2. ECHIPAMENT: Cabinet PLC 06-NK3
3. PARAMETRI/CARACTERISTICI ECHIPAMENT:

SURSA ALIMENTARE

Allen–Bradley Rockwell Automation

ControlLogix AC Power Supply

1756-PA75 B

- 1 buc

4. DEFECTIUNI CONSTATATE:

Reseteaza aleator PLC-ul

5. CAUZE POSIBILE: defect electronic

6. FIRMA REPARATOARE: -

7. ANUL PIF: -

8. PROPUNERI DE REMEDIERE: Inlocuire

9. DOCUMENTE ANEXATE:

10. SARCINA APROVIZIONARE: PLK

11. TERMEN ESTIMAT DE REMEDIERE:

Inlocuit cu rezerva

INTOCMIT



LUAT LA CUNOSTINTA



DAIS-1122-05.03.21