

NOTA DE CONSTATARE

Nr. 4 / Data 19.02.2019

1. INSTALATIA: ARIA 1
2. ECHIPAMENT: DCS – Statie de lucru DELL T3600 / Service Tag: 4JRVV22
3. PARAMETRI/CARACTERISTICI ECHIPAMENT:
 PLACA GRAFICA AMD FirePro MODEL V4900 - 1 buc
4. DEFECTIUNI CONSTATATE: nu functioneaza
5. CAUZE POSIBILE: defect electronic
6. FIRMA REPARATOARE: -
7. ANUL PIF: 2015
8. PROPUNERI DE REMEDIERE: Inlocuire
9. DOCUMENTE ANEXATE:
10. SARCINA APROVIZIONARE: PLK
11. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Nicolae N
[Signature]

LUAT LA CUNOSTINTA

[Signature]



DAIS-0644-04.04.19

NOTA DE CONSTATARE

Nr. 5 / Data 19.02.2019

1. INSTALATIA: ARIA 1
2. ECHIPAMENT: DCS – Statie de lucru DELL T3600 / Service Tag: 4QRVV22
3. PARAMETRI/CARACTERISTICI ECHIPAMENT:
 PLACA GRAFICA AMD FirePro MODEL V4900 - 1 buc
4. DEFECTIUNI CONSTATATE: nu functioneaza
5. CAUZE POSIBILE: defect electronic
6. FIRMA REPARATOARE: -
7. ANUL PIF: 2015
8. PROPUNERI DE REMEDIERE: Inlocuire
9. DOCUMENTE ANEXATE:
10. SARCINA APROVIZIONARE: PLK
11. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Nicolae N
[Signature]

LUAT LA CUNOSTINTA

[Signature]



DAIS-0644-04.04.19