

S.C. PETROTEL-LUKOIL S.A.

Catre
Director General Adjunct Reparatii si Mentenanta
Utilaje
I. Erogov

Privind Reparatie analizor H2S 10-AT-013

NOTA DE ACHIZITIE

Achizitionare piese reparatie analizor

No	Denumire material solicitat	Cantitate	Unitate de masura	Justificare achizitie	Termen necesar de livrare	Buget	Valoare Estimata	Numar necesar SAP(63)/ Numar comanda TORO(18)
1.	Metali cabinet, IP54, insulated, 1800x600x600mm	1	buc	reparatie	15 iulie 2013	Materiale si piese de schimb	470 euro	-
2.	Chiler/dryer M&C EC-EX, II G EEx pedq [ib] IIC T4	1	buc	reparatie	15 iulie 2013	Materiale si piese de schimb	4674 euro	-
3.	Heater 150W explosion proof integral Ex thermostate	1	buc	reparatie	15 iulie 2013	Materiale si piese de schimb	475 euro	-
4.	Sampling components, valves	1	buc	reparatie	15 iulie 2013	Materiale si piese de schimb	126 euro	-
5.	Others, junction box	1	buc	reparatie	15 iulie 2013	Materiale si piese de schimb	64	-

Sef serviciu

C. Alupoaicei



I. Ene
3018