

NOTA DE CONSTATARE

Nr. 6 / Data 01.03.2019

1. INSTALATIA: CRACARE
2. ECHIPAMENT: DCS – APP-WS-02
3. PARAMETRI/CARACTERISTICI ECHIPAMENT:
4. PARAMETRI/CARACTERISTICI ECHIPAMENT:
5. Dell WPJY9 Hard Drive 600GB 15K SAS 2.5" in Hybrid Tray ,
AL13SXL600N - 1 buc
6. DEFECTIUNI CONSTATATE: nu functioneaza
7. CAUZE POSIBILE: defect electronic
8. FIRMA REPARATOARE: -
9. ANUL PIF: 2014
10. PROPUNERI DE REMEDIERE: Inlocuire
11. DOCUMENTE ANEXATE:
12. SARCINA APROVIZIONARE: PLK
13. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Niinae Nicolae
C.N.

LUAT LA CUNOSTINTA

Ex



DAIS-0646-05.04.19

NOTA DE CONSTATARE

Nr.7 / Data 08.03.2019

1. INSTALATIA: TUC-DCS
2. ECHIPAMENT: DCS – PRO PLUS, S.T.:1K14032
3. PARAMETRI/CARACTERISTICI ECHIPAMENT: Server DCS
4. PARAMETRI/CARACTERISTICI ECHIPAMENT:
5. Dell WPJY9 Hard Drive 600GB 15K SAS 2.5" in Hybrid Tray ,
AL13SXL600N - 1 buc
6. DEFECTIUNI CONSTATATE: nu functioneaza
7. CAUZE POSIBILE: defect electronic
8. FIRMA REPARATOARE: -
9. ANUL PIF: 2014
10. PROPUNERI DE REMEDIERE: Inlocuire
11. DOCUMENTE ANEXATE:
12. SARCINA APROVIZIONARE: PLK
13. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Nimic Nicolae
Gh

LUAT LA CUNOSTINTA

Gh



DAIS-0646-05.04.19

NOTA DE CONSTATARE

Nr. 8 / Data 12.03.2019

1. INSTALATIA: COCSARE
2. ECHIPAMENT: DCS – APP-WS-03
3. PARAMETRI/CARACTERISTICI ECHIPAMENT: Server DCS
4. Dell WPJY9 Hard Drive 600GB 15K SAS 2.5" in Hybrid Tray ,
AL13SXL600N - 1 buc
5. DEFECTIUNI CONSTATATE: nu functioneaza
6. CAUZE POSIBILE: defect electronic
7. FIRMA REPARATOARE: -
8. ANUL PIF: 2014
9. PROPUNERI DE REMEDIERE: Inlocuire
10. DOCUMENTE ANEXATE:
11. SARCINA APROVIZIONARE: PLK
12. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Nicolae Nicolae
[Signature]

LUAT LA CUNOSTINTA

[Signature]



DAIS-0646-05.04.19

NOTA DE CONSTATARE

Nr.9 / Data 20.03.2019

1. INSTALATIA: TUC-DCS
2. ECHIPAMENT: DCS – PRO PLUS, S.T.:1K14032
3. PARAMETRI/CARACTERISTICI ECHIPAMENT: Server DCS
4. PARAMETRI/CARACTERISTICI ECHIPAMENT:
5. Dell WPJY9 Hard Drive 600GB 15K SAS 2.5" in Hybrid Tray ,
AL13SXL600N - 1 buc
6. DEFECTIUNI CONSTATATE: nu functioneaza
7. CAUZE POSIBILE: defect electronic
8. FIRMA REPARATOARE: -
9. ANUL PIF: 2014
10. PROPUNERI DE REMEDIERE: Inlocuire
11. DOCUMENTE ANEXATE:
12. SARCINA APROVIZIONARE: PLK
13. TERMEN ESTIMAT DE REMEDIERE:

INTOCMIT

Nimic Nicolae
[Signature]

LUAT LA CUNOSTINTA

[Signature]



DAIS-0646-05.04.19