

APROBAT,
MEMBRU AL DIRECTORATULUI-ING SEF
DANULESCU DAN

13.07.2018

RAPORT DE INSPECTIE
Nr. 428 Data: 12.07.2018

1. INSTALATIA: COCSARE


2. DENUMIRE ECHIPAMENT: Manometru cu flansa

3. PARAMETRI:

Parametrii conform proiect / livret utilaj
P = 0-6 bar
Serie 705-1

4. DEFECTIUNI CONSTATATE:

Capsula deformata.



5. CAUZE POSIBILE:

Depresiune.

6. PROPUNERI REMEDIERE DEFECTIUNI:

Inlocuire.

7. TERMEN DE REALIZARE:

Conform planificarii.

8. RECOMANDARI SUPLIMENTARE:

9. DOCUMENTE ANEXATE:

10. INSPECTOR SEF - SEF SIE - FIABILITATE

N.P. Alexandru Valentin

SEM NATURA.....

12.INTOCMIT

SPECIALIST ELECTROENERGETICIAN

N.P. Serbanescu Nicolae

SEM NATURA.....

11. ING. SEF METROLOG

N.P. Ene Ion

SEM NATURA.....



DAIS-0469-17.07.18